



Joe Construction Inc. / 07 Aug 2019 / Shee Arnai

Dust Risk Assessment Template


Complete

Inspection score	Failed items	Created actions
80.00%	0	1
Site Joe Construction Inc.		
Date and Time of Assessment 📅 7th Aug, 2019 ⌚ 7:00 AM +08		
Safety Officer (Full Name) Shee Arnai		
Location 186 Exhibition St, Melbourne VIC 3000, Australia		

Actions

1 Actions

SafetyCulture Staff created a High priority action

To Do  14th Aug, 2019 8:00 AM +08

Provide respirator mask

Carl, please provide respirator mask for Jason.

Inspection / Hazard / Hazard 1 / Controls

Select control measures

Overview

Description of procedure, task or worksite being assessed
 Water pipeline construction

Risk Matrix and Hierarchy of Controls

Risk Matrix Reference:

Risk Matrix

Likelihood		Very Likely	Likely	Unlikely	Highly Unlikely
Consequences	Fatality	High	High	High	Medium
	Major Injuries	High	High	Medium	Medium
	Minor Injuries	High	Medium	Medium	Low
	Negligible Injuries	Medium	Medium	Low	Low


Hierarchy of Controls Reference:



Hazard

Hazard 1

Description of hazard
 Road drill - inhalation of construction dust

Photo of hazard (optional)	
<p>– Photos</p>  <p>Photo 1</p>	
Type of Dust	Respirable dust
<p>– Notes</p> <p>The magnitude of potential dust emissions from construction works would be medium</p>	

Risk Rating

Consequences	Major Injuries
Likelihood	Unlikely
Risk Rating (refer risk matrix above)	Medium

Controls

1 Actions

Select control measures	<ul style="list-style-type: none"> + Engineering Controls + PPE
<p>– Actions</p> <hr/> <p>To Do Provide respirator mask</p>	
<p>Description of support measures</p> <ul style="list-style-type: none"> - Put barricade to isolate drill operation from pedestrians - Wear appropriate PPE (respirator mask) 	

Hazard 2

<p>Description of hazard</p> <p>Truck out - inhalation of construction dust</p>
<p>Photo of hazard (optional)</p> <p>Unanswered</p>

Type of Dust	Inhalable dust
--------------	----------------

– Notes
 The magnitude of potential dust emissions from track out could be medium at receptor locations in close proximity to the temporary haul roads.


Risk Rating

Consequences	Minor Injuries
Likelihood	Likely
Risk Rating (refer risk matrix above)	Medium

Controls

Select control measures	Administrative Controls
Description of support measures - Ensure driver receives proper training on load handling	

Completion

Recommendations Administer recommended controls identified in this report
Name and Signature of Safety Officer <div style="display: flex; align-items: center;">  <div> <p>Shee Arnai</p> <p>7th Aug, 2019 11:38 AM +08</p> </div> </div>

Photos

1 Photos



Photo 1