



## Car Maintenance Checklist

4S3BMHB68B3286050 / 30 Apr 2021 / Carl Josef Barbs

Complete

Score	84.62%	Failed items	2	Actions	1
VIN	4S3BMHB68B3286050				
Conducted on	30th Apr, 2021				
Prepared by	Carl Josef Barbs				
Location	Campbells Ford Trail, Greendale NSW 2745, Australia (-33.9569253, 150.6269426)				

## Failed Items & Actions

2 failed, 1 action

### Failed items

2 failed, 1 action

Inspection / Car Maintenance / Basic car maintenance

#### Tires



Screw found on the left fron tire



Photo 1

To do | Priority High | Due 30th Apr, 2021 3:30 PM PST | Created by SafetyCulture Staff

#### Needs repair

Hi Sef, Can you check this for me. thanks

Inspection / Car Maintenance / 3 months or 3,000 miles maintenance

#### Power steering fluid



Below normal level, This has been replenished

### Other actions

0 actions

## Inspection

1 action, 2 failed, 84.62%

## Car Maintenance

1 action, 2 failed, 84.62%

### Type of Car Maintenance

Basic Maintenance

3,000 Miles Maintenance

### Basic car maintenance

1 action, 1 failed, 80%

#### Engine lights

✓

#### Brake

✓

#### Tires

×

Screw found on the left front tire



Photo 1

To do | Priority High | Due 30th Apr, 2021 3:30 PM PST | Created by SafetyCulture Staff

#### Needs repair

Hi Sef, Can you check this for me. thanks

#### Lights

✓

#### Wipers

✓

### 3 months or 3,000 miles maintenance

1 failed, 87.5%

#### Automatic transmission fluid

✓

#### Power steering fluid

×

Below normal level, This has been replenished

#### Engine air filter

✓

#### Battery

✓

#### Belts

✓

#### Hoses

✓

#### Exhaust

✓

#### Tire treads

✓

## Completion

---

### Recommendations

Redo the inspection on tires. Check the pressure after repair.

---

### Inspected by (Name and Signature)



**Carl Josef Barbs**

30th Apr, 2021 10:03 AM PST

---

## Appendix



Photo 1