



Manufacturing Equipment Inspection by Mitti

11 Mar 2022 / Richelle Fontain

Complete

Score	88.89%	Failed items	1	Actions	1
Conducted on	11 Mar 2022 15:03 PST				
Prepared by	Richelle Fontain				
Location	20425 N Macarthur Ave, Blanchard, OK 73010, USA (35.0065827, -97.618872)				

Failed Items & Actions

1 failed, 1 action

Failed items

1 failed, 1 action

Inspection

Are safety guards in place on machinery and secured with approved fasteners?

No



Photo 2

To do | Assignee **Liam Dent** | Priority **High** | Due **18 Mar 2022 15:51 PST** | Created by **SafetyCulture Staff**

Install machine guarding

Other actions

0 actions

Inspection

1 action, 1 failed, 88.89%

Are all tools and equipment maintained and regularly serviced?

Yes

When was the last service conducted by the equipment maintenance specialist?

4 Mar 2022

Are all tools and equipment stored appropriately when not in use and after hours?

Yes

Is the machinery in good working order?

Yes



Photo 1

Are safety guards in place on machinery and secured with approved fasteners?

No



Photo 2

To do | Assignee **Liam Dent** | Priority **High** | Due **18 Mar 2022 15:51 PST** | Created by **SafetyCulture Staff**

Install machine guarding

Are there any damaged emergency stop buttons?

N/A

Are isolation and emergency cut-off switches operational?

Yes

Are control panels locked and secured?

Yes

Is machinery turned off when maintenance work is carried out?

Yes

Are all operators of equipment instructed, trained and supervised in how to use it safely?

Yes

Do operators of equipment have the appropriate licence where necessary (e.g. forklifts)?

Yes

Appendix




Photo 1



Photo 2