



Site Investigation Report Template

West coast project / 4 Mar 2019 / Erick Brent

Complete

Score	0%	Flagged items	0	Actions	0
Site	West coast project				
Location	2370 Humboldt Rd, Chico, CA 95928, USA				
Full Name of Investigator	Erick Brent				
Date of Investigation	04.03.2019 12:47 PST				

Inspection

Site Investigation Report

Authorization

I certify that I am the authorized representative and have the authority to grant the investigator access to the property for and authorize the work certified in this site investigation.

Full Name and Signature of Authorized Representative



John Flores
04.03.2019 12:48 PST

Site Information

Property Owner

Mary LLC

Address

2370 Humboldt Rd, Chico, CA
95928, USA

Latitude & Longitude

39.74001 / -121.793383

Climate

Sunny

Elevation

60 meters

Soil Characterization Method

Test Hole No.

1

Texture

Texture

Loam

Sand Sizes

Fine



Photo 1


Structure

Grade

Strong

Size

Coarse

Shape	Granular
Rock Fragments	
Rock Fragments	Irregular
Type of Rock	Sandstone
	
Photo 2	
Terms of Rock	Stratified
Mottles	
Quantity	Common
Size	Medium
Contrast	Distinct
Boundary	
Distinctness	Gradual
Topography	Irregular
Consistency	
Dry	Slightly Hard
Moist	Friable

Completion

Overall Findings

Based on today's site investigation, the site is ideal for our project and there are no foreseeable risks aside from the fire risk west of the city (California fires 2018). Visual inspection do not show soil contamination and no nearby industrial activities. Will still wait for the result of the lab testing of soil samples to be conclusive for the geotechnical report.

I certify that I am qualified to conduct and have completed this site investigation to the best of my knowledge.

Full Name and Signature of Investigator



Erick Brent
04.03.2019 12:55 PST

Appendix



Photo 1



Photo 2