



# Construction Site Workplace Safety Checklist

Bricks and Nails Inc. / Manuel Uy-Si / 8 May 2023

**Complete**

<b>Score</b>	<b>96.05%</b>	<b>Flagged items</b>	<b>3</b>	<b>Actions</b>	<b>0</b>
<b>Company</b>	Bricks and Nails Inc.				
<b>Inspected by</b>	Manuel Uy-Si				
<b>Conducted on</b>	08.05.2023 09:24 PST				
<b>Location</b>	Howard Ave, New Orleans, LA, USA (29.9538224, -90.0892731)				

**Flagged items**

3 flagged

Audit / General Site Tidiness and Accessways

**Stairways and accessways clear**

Non-Compliant

Some employees use a stair step as a resting chair.

Audit / Electrical Equipment/Plant

**Adequate temporary lighting**

Non-Compliant

Audit / Scaffolding – Planks Secured

**Platforms trip free**

Non-Compliant

**Audit**

3 flagged, 96.05%

## Site Control

100%

**Hazard board and signage up-to-date**

Compliant

**Environmental plans/measures**

Compliant

**Toolbox talk last date**

01.05.2023

**Safety inductions for all on site**

Compliant

**Safety notice board current**

Compliant

## Site Facilities

100%

**Offices clean, adequate & good lighting**

Compliant

**Smoko sheds – clean, potable water**

Compliant

**Tool/equipment sheds adequate**

Compliant

Everything's well kept.

**Toilets – clean, washing water**

Compliant

## General Site Tidiness and Accessways

1 flagged, 75%

**Clear, safe access to work areas**

Compliant

**Stairways and accessways clear**

Non-Compliant

Some employees use a stair step as a resting chair.

**Hoardings/fence and gates secure**

Compliant

**Loose materials secure from wind**

Compliant

## Personal Protective Equipment

100%

**Signage displayed and legible**

Compliant

All good.



Photo 1

**Hardhats being worn**

Compliant

**Correct footwear being worn**

Compliant



Photo 2

**Glasses/ear muffs/vests/masks used**

Compliant

**Hazard evaluations been performed and certified**

Compliant

**Protective equipment adequate for exposure**

Compliant

**Employees issued with PPE where needed**

Compliant

**PPE being used and are in good condition**

Compliant

**Inspections being conducted before and after use of PPE**

Compliant

**Adequate maintenance and sanitary storage available and used**

Compliant

**Adequate fall protection provided**

Compliant

**Eye protection available**

Compliant

**Face protection (glasses, goggles, shields) available and are in good condition**

Compliant

**Hearing protection available**

Compliant

And let me borrow one, too! Nice.



Photo 3

**Respirators and masks provided**

Compliant

**Respirators used to protect against harmful dust, asbestos, sand blasting, and welding (lead, paint, and galvanized zinc or cadmium)**

Compliant

<b>Head protection available</b>	Compliant
<b>Hand and foot protection available</b>	Compliant
<b>Physical exams performed as required</b>	Compliant
Done every quarter.	

## Fire Extinguishers and Fire Protection

100%

<b>Fire extinguishers fully charged, operable, and kept in designated places at all times</b>	Compliant
<b>Portable fires extinguishers inspected monthly</b>	Compliant
<b>Employees are expected to use fire extinguishers, they've been trained in the general principles of fire extinguisher use and hazards involved with the incipient stage of firefighting</b>	Compliant
<b>Fire alarm system tested annually</b>	Compliant

## Emergency Evacuation

100%

<b>Written emergency and fire prevention plans made available to building occupants for review</b>	Compliant
<b>Occupants been trained in emergency evacuation of the building</b>	Compliant
<b>Emergency drills conducted on a routine basis</b>	Compliant

## Cranes/Hoist/Lifting Equipment

100%

<b>Proper lift assessment plan done</b>	Compliant
<b>Crane certification current</b>	Compliant
<b>Slings/chains certified</b>	Compliant
<b>Operator procedures in place</b>	Compliant
<b>Inspections being done</b>	Compliant
Mr. Lim is doing a good job about regular inspections!	
<b>Man cage available</b>	Compliant
<b>Emergency plan in place</b>	Compliant

## Compressed Air Equipment

100%

In good condition	Compliant
Appropriate guards fitted	Compliant
Trained user	Compliant

## Excavations

100%

Correctly shored	Compliant
Access controlled	Compliant

## Hot Works

100%

Hot work permits being issued	Compliant
Fire extinguishers on hand	Compliant
Operators using PPE	Compliant

## Electrical Equipment/Plant

1 flagged, 87.5%

Main board lockable/weatherproof	Compliant
Current tagged and damage-free leads	Compliant
Current tagged plant	Compliant
Current tagged lifeguards	Compliant
Leads safely placed	Compliant
Electrical equipment/plant – good condition	Compliant
Electrical equipment/plant – appropriate guards on plant	Compliant
Adequate temporary lighting	Non-Compliant

## Scaffolding – Planks Secured

1 flagged, 90.91%

Notifiable weekly Scaftag/current	Compliant
Handrails/mid-rails	Compliant
Toe boards	Compliant

<b>Platforms</b>	Compliant
<b>Ladders/stairs</b>	Compliant
<b>Base sound</b>	Compliant
Super sturdy!	
<b>Work platforms clear</b>	Compliant
<b>Platforms trip free</b>	Non-Compliant
<b>Planks tied down</b>	Compliant
<b>Headroom clear</b>	Compliant
<b>Ties/bracing adequate</b>	Compliant

## Ladders

100%

<b>Good condition</b>	Compliant
<b>Secured top and bottom</b>	Compliant
<b>Stays to step ladders</b>	Compliant
<b>Working 2 steps down</b>	Compliant

## Completion

### Additional recommendation

Left notes for non-compliant items. Please take action ASAP, work will be affected if not addressed.

### Full Name & Signature of Inspector



Manuel Uy-Si  
08.05.2023 09:30 PST

## Media summary



Photo 1



Photo 2



Photo 3